

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20160516-E483469  
**Report Reference** E483469-20150516  
**Issue Date** 2016-MAY-16

**Issued to:** BTICINO COSTA RICA S A  
100 Norte de CENADA  
Barreal de Heredia COSTA RICA

**This is to certify that representative samples of** GROUND-FAULT CIRCUIT INTERRUPTERS  
AP1228GF and PU1228GF

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 943, GROUND-FAULT CIRCUIT-INTERRUPTERS  
**Additional Information:** See the UL Online Certifications Directory at [www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

