

CERTIFICATE OF COMPLIANCE

Certificate Number 20160516-E483469
Report Reference E483469-20150516
Issue Date 2016-MAY-16

Issued to: BTICINO COSTA RICA S A
100 Norte de CENADA
Barreal de Heredia COSTA RICA

This is to certify that representative samples of GROUND-FAULT CIRCUIT INTERRUPTERS
AP1228GF and PU1228GF

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 943, GROUND-FAULT CIRCUIT-INTERRUPTERS
Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

